

## IAINI

NEVER exceed the maximum running speed (4,500rpm).

GENERAL SAFETY PRECAUTIONS

NEVER apply excess pressure, ALWAYS allow the tool to do the work.

ALWAYS inspect the brush for defects/damage before using, if in doubt DO NOT use.

ALWAYS ensure the drill is switched OFF and isolated from the main electrical supply before fitting/removing brushes.

supply before inting/removing brushes.

ALWAYS ensure the brush is firmly secured before switching ON.

ALWAYS wear safety goggles, manufactured to the latest European Safety

Standards. Everyday eyeglasses do not have impact resistant lenses, they

are not safety glasses.

ALWAYS use a face or dust mask if operation is particularly dusty.

ALWAYS keep children away. All visitors should be kept a safe distance

from the work area, especially whilst working with tools, in particular power tools.

ALWAYS concentrate on the job in hand, no matter how trivial it may seem. Be aware that accidents are caused by carelessness due to familiarity.